

The fire in your ATV

Copperhead EFI Application Release Notes

Get the latest version at: http://www.velocitydevices.com.

Version 1.0 (December 20, 2005)

Features:

- Initial Release

Known Bugs:

- Every time the pod is connected to the computer, and a map download is initiated, it will timeout and fail. It will succeed the second time.
- The print function produces an illegible plot.
- There is no program map pull down menu.
- The default map #1 generated by the software is different from the map shipped with the CDI. Instead of clicking on "Load Default". Use "Open" and select the "default.pod" file.
- When the pod is programming, pressing the "OK" or "CANCEL" button will abort the programming. This leaves the pod with incomplete data. The pod must be FULLY programmed before it is connected to the CDI.

Version 1.1 (January 10, 2006)

Features:

- Menus were arranged and cleaned up to provide a more intuitive interface.
- Added support for programming CDI firmware files.

Known Bugs:

- Every time the pod is connected to the computer, and a map download is initiated, it may timeout and fail. It will succeed the second time.
- The print function produces an illegible plot.

Telephone: (403) 668-7470
Facsimile: (403) 668-7471
Webpage: www.velocitydevices.com
Email: tech@velocitydevices.com